

IMPORTANT RECALL NOTICE

Specialized 2008 and 2009 Model Year Globe Bicycles with Kinesis Aluminum Forks equipped with Aluminum Alloy Steerer Tubes:

Sold from July 2007 to September 2012

The front fork steerer tube can break, posing a fall hazard.

Remedy:

Stop riding these bicycles immediately and return your bicycle to an Authorized Specialized Retailer for a free replacement fork.

Affected Bicycles:

2008 Globe Elite*	2009 Globe Vienna 3*
2008 Globe Sport*	2009 Globe Vienna 3 Disc
2008 Globe Sport Disc	2009 Globe Vienna 4*
2008 Globe Centrum Comp	2009 Globe Vienna Deluxe 3
2008 Globe Centrum Elite	2009 Globe Vienna Deluxe 4*
2008 Globe City 6*	2009 Globe Vienna Deluxe 5
	2009 Globe Vienna Deluxe 6

*Signifies women's models as included.

If you have any questions contact Specialized at:

(822) 687-1119

or visit their web site at:

www.specialized.com

Pour la version français visiter : <http://www.hc-sc.gc.ca>

IMPORTANT RECALL NOTICE

2008 Globe Elite



2008 Globe Elite Wmn.



2008 Globe Sport



2008 Globe Sport Wmn.



2008 Globe Sport Disc



2008 Globe Centrum Comp



2008 Globe Centrum Elite



2008 Globe City 6



IMPORTANT RECALL NOTICE

2008 Globe Citv 6 Wmn.



2009 Globe Vienna 3



2009 Globe Vienna 3 Wmn.



2009 Globe Vienna 3 Disc



2009 Globe Vienna 4



2009 Globe Vienna 4 Wmn.



2009 Globe Vienna Deluxe 3



2009 Globe Vienna Deluxe 4



IMPORTANT RECALL NOTICE

2009 Globe Vienna Deluxe 4
Wmn



2009 Globe Deluxe 5



2009 Globe Deluxe 6

